



Plibrico Company Cement Kiln Application Guide




Grate Cooler	Planetary Cooler
<i>Drop Out Zone</i> Plicast / Plishot: HyMOR 3100 SP Plicast / Plishot: HyREZIST 3000	<i>Outlet Ports</i> Plicast / Plishot: HyMOR 3100 SP Plicast Super HyMOR 80
<i>Bull Nose</i> Plicast HyMOR 3100 SP Plibrico 68 SA	<i>Elbows</i> Plicast HyMOR 3100 SP Plicast Super HyMOR 80
<i>Side Wall & Roof</i> Plicast / Plishot: HyREZIST 3000	<i>Redi-Shape Precast Cooler</i> Plicast / Plishot: HyMOR 3100 SP
<i>Curbs</i> Plicast / Plishot: HyMOR 3100 SP Plicast / Plishot: HyREZIST 3000	Plicast / Plishot: HyREZIST 3000 Pligun HyMOR 8 Pligun HyREZIST 2700



	Stage 4 Cyclones Lower Preheat Riser Lower Precaliner Riser	Tail Ring	Burner Tube
<i>Normal Service</i>	Pligun HyREZIST 2700	Nose Ring	Plicast HyMOR 3100 SP Redi-Shape Precast
<i>Moderate Alkali Build-up</i>	Plicast / Plishot: HyMOR SiC 30 Si-Bond SD Pligun HyREZIST SiC 30	Kiln Preheat Zone	Firing Hood
<i>High Alkali Build-up</i>	Plicast / Plishot: HyMOR SiC 50 Si-Bond SP Pligun HyREZIST SiC 50	Plicast / Plishot: HyMOR 3100 SP Plicast / Plishot: HyREZIST 3000 Pligun HyREZIST 2700	Plicast HyMOR 3000 Plishot HyREZIST 3000 Plibrico Super F AB Plibrico 60 AB Pligun HyREZIST 2700

Application Note



*Waste—Tires, Haz. Waste, etc



Plibrico Company LLC

1010 North Hooker Street
Chicago, Illinois 60622

Tel: 312- 337-9000

Fax: 312- 337-9003

www.plibrico-usa.com

This application guide is intended for general information only. Please consult Plibrico Company or your local Plibrico Representative for specific application assistance and product recommendations.